

PROFORMA FOR SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

No. 4499

Dated: 11/03/24

It is certified that an inspection team headed by Aashish Kumar Gupta(Name of Officers with designation) from Sub engineer(Name of Department / Office) inspected the MAHARISHI VIDYA MANDIR, MANGLA,BILASPUR (C.G.) 495001 (Name & Address of the school) on 07/03/24 (date ofinspection) and found that the MAHARISHI VIDYA MANDIR (Name of school) has safe

drinking water facilities for the students and members of staff of the institution and is

maintaining the hygienic sanitation condition in the school building & the campus as per

norms prescribed by the Central/ State/ U.T. Govt.

The above is valid for a period of 2024-2025Signature with Seal: R. AgnaniName: R. AgnaniDesignation: Z.C. SAKRI 2-01Name & Address of Department /Office: N.P.N. BilaspurTo
MAHARISHI VIDYA MANDIR, MANGLA,
BILASPUR (C.G.)
Pin No. 495001

(Name & Address of the Institution)

* The filled up certificate should be either in Hindi or English. If it is issued in vernacular language, translated notarized version in English be uploaded along with the original vernacular certificate as a single pdf.

(1/03) श्रीमान्
जी. पी. कोमलेश्वर
महाराष्ट्र शासन
जिला स्वास्थ्य
विभाग
राज्य पब्लिक हेल्थ
अधिकारी
बिलासपुर (उ.प्र.)Principal
Maharishi Vidya Mandir
Mangla, Bilaspur (C.G.)